


Appendix B – Inspection Required for Permit Processing

Page intentionally blank



U.S. Army
Corps of Engineers
Nashville District
Regulatory Branch
SECTION - WEST

COMPLIANCE INSPECTION REPORT

PERMIT NO. 200702181

Compliance [] Noncompliance []

PERMITTEE: Billy Christopher, d/b/a River Front Development, LLC
ADDRESS: 211 South Jefferson Street
Athens, Alabama 35611
Telephone: 256-232-7072

LOCATION: Mile 7.3R, Elk River, Wheeler Lake, Limestone County, AL

LATITUDE: 34.832

LONGITUDE: -87.208

QUAD: Cairo, AL

Type of Work: proposed dredging, community dock, riprap, and ramp.

Permit Type: IP X NWP _____ Regional GP _____ Other _____

Status of Work: On-Going _____ Completed _____

On 03/12/08, I inspected the location for Mr. Christopher's proposed facilities. The site was located between two steep hills in a narrow cove off the right descending bank of Elk River. No wetlands were evident in the area. Substrate was comprised of rock, cobble, and silt.


ATTACHMENTS: Project Drawings _____ Photographs x _____

Jurisdictional Determination 10 and 404 _____

Other _____

Date of Inspection: 03-12-08

Inspector: Richard Graham



File No. 200702181, Billy Christopher site, 03/12/08.