

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No. 128	Date: 2-3-2009		
Direction Photo Taken: Looking east.			
Description: White plastic strap lawn chair.			

Photo No. 129	Date: 2-4-2009		
Direction Photo Taken: Looking northeast.			
Description: Remnants of clay cover from C-Dike washed by water over the peninsula between Slough 3 and the Emory River. Note: no ash present around the clay cover material.			

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 130	Date: 2-4-2009		
Direction Photo Taken: Looking west-southwest.			
Description: 5/8-inch steel cable (looped or two cables) encased in woven geotextile. Nearby is a piece of corrugated PE (8-inch). Geotextile and #57 stone are most likely associated with the corrugated pipe.			

Photo No.: 131	Date: 2-4-2009		
Direction Photo Taken: Looking west.			
Description: Heavy gauge iron pipe, originally 3" square, painted yellow. Part of a gate? See also Photo 133.			

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 132	Date: 2-4-2009		
Direction Photo Taken: Looking north.			
Description: Yokohama brand truck tire filled with concrete with round metal pipe at the center. Possibly a base for a sign or mailbox.			

Photo No.: 133	Date: 2-4-2009		
Direction Photo Taken: Looking northeast.			
Description: Heavy gauge iron pipe, originally 3" square, painted yellow. Part of a gate? See also Photo 131.			


**RELIC IDENTIFICATION
PHOTOGRAPHIC LOG**

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 134	Date: 2-4-2009		
Direction Photo Taken: Looking northeast.			
Description: Remnant of C-Dike with native silt/silty sand located to the west of the damaged home on the peninsula between Slough 3 and the Emory River.			

Photo No.: 135	Date: 2-4-2009	
Direction Photo Taken: Looking north.		
Description: Native silt/silty sand from beneath C-Dike or backwater bottom pushed onto the lawn to the west of the damaged home on the peninsula between Slough 3 and the Emory River.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 136	Date: 2-4-2009		
Direction Photo Taken: Looking northeast.			
Description: Scattered concrete blocks. Some blocks are standard size (8-inch), others are thinner. All bricks are painted on at least one side.			

Photo No.: 137	Date: 2-4-2009		
Direction Photo Taken: Looking north-northwest.			
Description: MC-6 channel steel filled with concrete at background (red arrow). Swimming pool filter box (yellow arrow).			

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 138	Date: 2-4-2009		
Direction Photo Taken: Looking east.			
Description: Section of dock or deck pushed into grape plantings located west-northwest of the damaged home on the peninsula between Slough 3 and the Emory River.			

Photo No.: 139	Date: 2-4-2009	
Direction Photo Taken: Looking south.		
Description: Remnant of C-Dike overtopped by ash.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 140	Date: 2-4-2009		
Direction Photo Taken: Looking northeast.			
Description: Relic ash block overtopped by ash in Slough 2.			

Photo No.: 141	Date: 2-5-2009		
Direction Photo Taken: Looking east.			
Description: Swimming pool cleaner hose located in Slough 3.			

**RELIC IDENTIFICATION
PHOTOGRAPHIC LOG**

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No. 60095742
Photo No. 142	Date: 2-5-2009		
Direction Photo Taken: Looking southwest.			
Description: Corrugated PE pipe (8-inch) in Slough 3. Note no geotextile or #57 stone around or near the pipe.			

Photo No. 143	Date: 2-5-2009	
Direction Photo Taken: Looking northwest.		
Description: Large concrete block. Possibly an anchor or base for structure (pier, etc.).		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 144	Date: 2-5-2009		
Direction Photo Taken: Looking west.			
Description: Corrugated, non-perforated PE pipe (8-inch) in Slough 3. Note no geotextile or #57 stone around or near the pipe.			

Photo No.: 145	Date: 2-5-2009	
Direction Photo Taken: Looking west.		
Description: Corrugated, non-perforated PE pipe (8-inch) in Slough 3. Note no geotextile or #57 stone around or near the pipe.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 146	Date: 2-5-2009		
Direction Photo Taken: Looking north.			
Description: Outdoor light fixture “pumpkin” shaped with a stem-styled connection at the top.			

Photo No.: 147	Date: 2-5-2009	
Direction Photo Taken: Looking north.		
Description: Thin steel channel filled with concrete (red arrow). Possibly a doorframe.		

**RELIC IDENTIFICATION
PHOTOGRAPHIC LOG**

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No. 60095742
Photo No. 148	Date: 2-5-2009		
Direction Photo Taken: Looking south.			
Description: Light steel lawn edging (painted green).			

Photo No. 149	Date: 2-5-2009	
Direction Photo Taken: Looking north.		
Description: Heavy metal grate/walkway. Not heavy enough for vehicle traffic. A similar grate was observed in place on the northwest side of the bridge between the perimeter dike and the gravel stockpile. The in-place grate covered a corrugated steel drain pipe.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 149_A	Date: 2-5-2009		
Direction Photo Taken: Vertical.			
Description: Face from a combination clock/thermometer in Slough 3.			

Photo No.: 150	Date: 2-5-2009	
Direction Photo Taken: Looking west.		
Description: Post with attached electrical connection and adjacent yard hydrant. Likely associated with dock. Electrical wire stretched out to the north.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 150_2	Date: 2-5-2009		
Direction Photo Taken: Looking northeast.			
Description: Garden hose illustrates direction of movement.			

Photo No.: 151	Date: 2-5-2009	
Direction Photo Taken: Looking northeast.		
Description: Dock sections. At right is dock constructed of treated lumber stringers and plastic, simulated wood grain decking. At left is a treated lumber dock with boat bumpers.		

**RELIC IDENTIFICATION
PHOTOGRAPHIC LOG**

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No. 60095742
Photo No. 152	Date: 2-5-2009		
Direction Photo Taken: Looking northeast.			
Description: 10-gallon water heater and garden hose and "GRIPTECH" football (red arrow in background).			

Photo No. 153	Date: 2-5-2009		
Direction Photo Taken: Looking northeast.			
Description: Section of pier, purple swim fin (red arrow).			

**RELIC IDENTIFICATION
PHOTOGRAPHIC LOG**

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 154	Date: 2-5-2009		
Direction Photo Taken: Looking northeast.			
Description: Floating boathouse/dock. Posts match location in Photo 153.			

Photo No.: 155	Date: 2-5-2009	
Direction Photo Taken: Looking west.		
Description: Swimming pool filter.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 156	Date: 2-5-2009		
Direction Photo Taken: Looking west.			
Description: C-Dike material in Slough 3.			

Photo No.: 157	Date: 2-5-2009	
Direction Photo Taken: Looking west.		
Description: C-Dike material in Slough 3 northeast of location shown in Photo 156.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 158	Date: 2-5-2009		
Direction Photo Taken: Looking northeast.			
Description: Black metal grate (red arrow) and unbroken 8-foot fluorescent light bulb in Slough 3.			

Photo No.: 159	Date: 2-5-2009	
Direction Photo Taken: Looking west.		
Description: Cattails and root balls from cattails in Slough 3.		

**RELIC IDENTIFICATION
PHOTOGRAPHIC LOG**

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No. 60095742
Photo No. 160	Date: 2-5-2009		
Direction Photo Taken: Looking north.			
Description: Vegetation (long grass) overtopped by ash in Slough 3.			

Photo No. 161	Date: 2-5-2009	
Direction Photo Taken: Looking northwest.		
Description: Remnants of C-Dike in Slough 3.		


RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 162	Date: 2-5-2009		
Direction Photo Taken: Looking northeast.			
Description: Beachcomber pontoon boat, Tennessee Registration Number TN 3573 DV with Lowe's aluminum johnboat, Tennessee Registration Number TN 7753 BJ wrapped over a section of dock.			

Photo No.: 163	Date: 2-5-2009		
Direction Photo Taken: Looking north.			
Description: Gray PVC electrical conduit (1.5-inch dia.).			

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 164	Date: 2-7-2009		
Direction Photo Taken: Looking east.			
Description: 8" x 8" Pyrex dish and 5-gallon pail on north shore of Emory River backwater.			

Photo No.: 165	Date: 2-10-2009	
Direction Photo Taken: Looking east.		
Description: Iron pipes (blue arrows) and railroad rail (red arrow) unearthed east of Swan Pond Road – inaccessible due to ditch and soft ash.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 166	Date: 2-10-2009		
Direction Photo Taken: Looking east.			
Description: Concrete pipe (red arrow), 18-20" in diameter and approximately 10-feet long along with a piece of drainage layer fabric (blue arrow). Inaccessible due to ditch and soft ash.			

Photo No.: 166_2	Date: 2-17-2009	
Direction Photo Taken: Looking south.		
Description: Corrugated metal pipe, 36-inches in diameter.		

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 167	Date: 2-17-2009		
Direction Photo Taken: Looking north.			
Description: Portion of corrugated metal pipe, likely a section of the pipe identified in Photo 166.			

Photo No.: 168	Date: 2-17-2009		
Direction Photo Taken: Looking southeast.			
Description: Corrugated metal pipe similar to the pipe shown in Photo 166.			

**RELIC IDENTIFICATION
PHOTOGRAPHIC LOG**

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No. 60095742
Photo No. 169	Date: 2-25-2009		
Direction Photo Taken: Looking .			
Description:			

Photo No. 170	Date: 2-25-2009		
Direction Photo Taken: Looking west.			
Description: Steel pipe unearthed by excavators.			

RELIC IDENTIFICATION PHOTOGRAPHIC LOG

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No.: 60095742
Photo No.: 171	Date: 3-11-2009		
Direction Photo Taken: Looking south.			
Description: PVC pipe 1-inch diameter.			

Photo No.: CHT-2	Date: 1-21-2009	
Direction Photo Taken: Looking vertical.		
Description: Survey monument CHT-2.		

**RELIC IDENTIFICATION
PHOTOGRAPHIC LOG**

Client Name: Tennessee Valley Authority		Site Location: Kingston Fossil Plant –Harriman, Tennessee	Project No. 60095742
Photo No. Scraper	Date: 2-25-2009		
Direction Photo Taken: Looking vertical/west.			
Description: Scraper formerly parked on Center Dike.			